



---

**Search Tags:** Deterioration

**Project Count:** 11

---



## Medford High School Pool

Medford, MA

**Project Contacts:** [Paul Kelley](#), [Matthew Sherman](#)


The swimming pool at Medford High School was constructed in 1970...

**Service:** [Materials Investigation](#), [Structural Investigation](#), [Structural Rehabilitation](#)

**Market:** [Education - K-12](#)

**Keywords:** [Concrete Rehabilitation](#), [Concrete](#), [Condition Assessment](#), [Construction Administration](#), [Corrosion](#), [Deterioration](#), [Laboratory Testing and Analysis](#), [Natatorium](#), [Petrography](#), [Non-Destructive Testing](#)

---



## War Memorial Pool Complex

Cambridge, MA

**Project Contacts:** [Paul Kelley](#), [Matthew Sherman](#)

The pool complex at the War Memorial Recreation Center was...

**Service:** [Materials Investigation](#), [Structural Investigation](#)

**Market:** [Sports & Entertainment](#)

**Keywords:** [Concrete Rehabilitation](#), [Condition Assessment](#), [Corrosion](#), [Deterioration](#), [Field Testing](#), [Laboratory Testing and Analysis](#), [Natatorium](#), [Petrography](#), [Non-Destructive Testing](#)



## Philipsburg Elementary School

Philipsburg, PA

**Project Contacts:** [Peter Nelson](#)

Completed in 2004, Philipsburg Elementary School is a two-story...

**Service:** [Materials Investigation](#)

**Market:** [Education - K-12](#)

**Keywords:** [Deterioration](#), [Flooring and Coatings](#), [Flooring](#), [Material-Related](#), [Materials Analysis](#), [Petrography](#)



## University of Connecticut, Beach Hall

Storrs, CT

**Project Contacts:** [Susan Knack-Brown](#), [Stephen Ruggiero](#)

Beach Hall, originally constructed in 1929, is a transitional masonry building with mass masonry walls and an embedded structural frame. The building features a slate mansard roof, low-slope...

**Service:** [Building Enclosure Investigation](#), [Building Enclosure Rehabilitation](#)

**Market:** [Education - College & Prep](#)

**Keywords:** [Deterioration](#), [Masonry-Transitional](#), [Masonry](#), [Preservation Technology](#) , [Water Leakage](#)



## University of Connecticut, Wood Hall

Storrs, CT

**Project Contacts:** [Susan Knack-Brown](#), [Stephen Ruggiero](#)

Wood Hall at the University of Connecticut (UConn), constructed in 1938, is a load-bearing brick masonry building with a gable roof and slate roofing. The masonry facade features decorative stone...

**Service:** [Building Enclosure Investigation](#), [Structural Investigation](#)

**Market:** [Education - College & Prep](#)

**Keywords:** [Cladding / Recladding](#), [Condition Assessment](#), [Deterioration](#), [Masonry-Brick](#), [Preservation Technology](#), [Walls](#), [Water Leakage](#)



## General Edwards Bridge

Lynn-Revere, MA

**Project Contacts:** [Paul Kelley](#)

The General Edwards Bridge is a multiple-span steel-girder bridge over the mouth of the Saugus River where it flows into the Atlantic Ocean. The central moveable span over the main navigation...

**Service:** [Structural Rehabilitation](#)

**Market:** [Bridge](#)

**Keywords:** [Bridge](#), [Major Vehicular](#), [Concrete](#), [Deterioration](#), [Emergency Response](#), [Field Testing](#), [Term Contracts](#)



## Middlebury College, Bread Loaf Mountain Campus

Middlebury, VT

**Project Contacts:** [Matthew Bronski](#), [Jeffry Ceruti](#), [Stephen Ruggiero](#)

The Bread Loaf Mountain Campus of Middlebury College is the home of the Bread Loaf School of English, the Bread Loaf Writer's Conference, and other summer programs run by the college. The campus...

**Service:** [Building Enclosure Rehabilitation](#), [Structural Rehabilitation](#)

**Market:** [Education - College & Prep](#)

**Keywords:** [Condition Assessment-Multi-Building](#), [Deterioration](#), [Historic](#), [Preservation Technology](#), [Wood Frame](#), [Wood](#)



## Ennis House

Los Angeles, CA

**Project Contacts:** [Carolyn Searls](#)

Designed by Frank Lloyd Wright in the Mayan Revival style, the Ennis House was constructed in 1924 and remains as one of his iconic "textile block" houses. The handmade,...

**Service:** [Building Enclosure Investigation](#)

**Market:** [Cultural](#)

**Keywords:** [Award Winning](#), [Concrete](#), [Condition Assessment](#), [Deterioration](#), [Historic](#), [Masonry-CMU](#), [National Register of Historic Places](#), [Preservation Technology](#)



## Water Research Foundation, Prestressed Concrete Cylinder Pipe Condition Assessment

United States

**Project Contacts:** [Rasko Ojdrovic](#)

Prestressed concrete cylinder pipe (PCCP) have been used for water transmission systems for more than sixty-five years. Therefore, utilities need effective means to identify distressed or...

**Service:** [Structural Investigation](#)

**Market:** [Water/Wastewater](#)

**Keywords:** [Codes & Standards](#), [Condition Assessment](#), [Deterioration](#), [PCCP](#), [Pipe](#), [Pipeline](#), [Research/Development](#)



## Youth Development Center, Brick Masonry Chimney Repair

Manchester, NH

**Project Contacts:** [Greggry Cohen](#), [Gustavo Tumialan](#)

The brick masonry chimney at the Manchester Youth Development Center (YDC) power plant is an 80 ft tall structure that vents the facility's boilers. Constructed in the first half of the 20th...

**Service:** [Structural Rehabilitation](#)

**Keywords:** [Chimney/Stack](#), [Concrete](#), [Deterioration](#), [Masonry-Brick](#), [Structural Stabilization](#)



## First Street Bridge

Boston-Cambridge, MA

**Project Contacts:** [Erik Farrington](#), [Paul Kelley](#)

The First Street Bridge is a bascule drawbridge carrying traffic westbound over Broad Canal. The bridge suffered from several forms of deterioration including damage to the concrete...

**Service:** [Structural Rehabilitation](#)

**Market:** [Bridge](#)

**Keywords:** [Concrete](#), [Deterioration](#), [Metal-Steel](#), [Metal](#), [Term Contracts](#)