



---

**Search Tags:** Condition Assessment-Multi-Building

**Project Count:** 17

---



## Archdiocese of Boston, Multiple Building Condition Assessments

**Boston, MA**

**Project Contacts:** [Paul Kelley](#), [Milan Vatovec](#)

With a need to evaluate more than 100 properties with a total of 200 individual structures, the Archdiocese of Boston asked SGH to develop and implement a condition assessment program that...

**Services:** [Building Enclosure Investigation](#), [Structural Investigation](#)

**Markets:** [Religious](#)

**Keywords:** [Condition Assessment-Multi-Building](#), [Religious](#), [Spire/Bell Tower](#), [Term Contracts and IDIQs](#)



## Bentley University, Campus-wide Condition Assessments

**Waltham, MA**

**Project Contacts:** [Gregory Doelp](#), [Philip Moser](#), [Eric Olson](#)

The Bentley University campus comprises more than forty buildings, including dormitories, offices, academic and function facilities, a gymnasium and natatorium, and parking garages. To better plan...

**Services:** [Building Enclosure Investigation](#), [Building Enclosure Rehabilitation](#)

**Markets:** [Education - College & Prep](#)

**Keywords:** [Condition Assessment-Multi-Building](#), [Curtain Wall](#), [Facade Inspection](#), [Masonry-Brick](#), [Roofing](#), [Roofing](#), [Low-Sloped](#), [Sealants and Coatings](#), [Stone-Slate](#)



## Catholic Schools

San Francisco, CA

Project Contacts: [Stephen Harris](#)

Based on recommendations from The Private Schools Earthquake Safety Working Group, the Earthquake Safety Implementation Program (ESIP) for the City and County of San Francisco worked with the...

Services: [Structural Investigation](#)

Markets: [Education - K-12](#)

Keywords: [Concrete](#), [Condition Assessment-Multi-Building](#), [Masonry](#), [Metal-Steel](#), [Seismic Engineering and Retrofit](#), [Wood](#)



## Roof Investigations

Northeastern United States

Project Contacts: [Pedro Sifre](#), [Joseph Zona](#)

During the 2014-2015 winter, historic amounts of snow fell in the Northeastern U.S. With closely spaced storms, the area experienced little or no melting between them. The resulting accumulation...

Services: [Structural Investigation](#)

Markets: [Manufacturing & Industrial](#)

Keywords: [Condition Assessment-Multi-Building](#), [Failure Investigation](#), [Snow and Ice](#), [Structural Adequacy Assessment](#)



## Landmarks Illinois

Hyde Park, IL

Project Contacts: [Peter Babaian](#)

As part of the Preservation Easement Program, Landmarks Illinois oversees the preservation of properties with designated easement on their facades. Working for Landmarks Illinois, SGH evaluated...

Services: [Building Enclosure Investigation](#)

Markets: [Other](#)

Keywords: [Condition Assessment](#), [Condition Assessment-Multi-Building](#), [Facade Inspection](#), [Facade Ordinance](#), [Historic](#), [Masonry-Brick](#)



## Duke University, Craven and Crowell Quadrangles

Durham, NC

**Project Contacts:** [Bradford Carpenter](#), [Nicholas Piteo](#), [Niklas Vigener](#)

Housing approximately 800 students, Craven and Crowell Quadrangles (Quads) make up a significant portion of Duke University's West Campus Quads. The university determined the 1920s structures,...

**Services:** [Building Enclosure Investigation](#)

**Markets:** [Education - College & Prep](#)

**Keywords:** [Air Infiltration](#), [Condition Assessment](#), [Condition Assessment-Multi-Building](#), [Dormitory](#), [Roofing](#), [Roofing](#), [Clay Tile](#), [Roofing](#), [Steep-Sloped](#), [Stone](#), [Windows](#)



## Duke University Medical Center, North Hospital Complex

Durham, NC

**Project Contacts:** [Bradford Carpenter](#), [Joseph Rogers](#), [Niklas Vigener](#)

The North Hospital Complex consists of several large buildings, including three patient towers to the west, a cylindrical elevator core, ancillary buildings, and a large atrium. Designed in the...

**Services:** [Building Enclosure Investigation](#), [Building Enclosure Rehabilitation](#)

**Markets:** [Health Care](#)

**Keywords:** [Condition Assessment-Multi-Building](#), [Skylight](#), [Stucco](#), [Water Leakage](#), [Windows](#)



## Asbury Methodist Village Apartment Homes

**Gaithersburg, MD**

**Project Contacts:** [Niklas Vigener](#)

The apartment homes at Asbury Methodist Village (Asbury) offer independent senior living options. Asbury wanted to renovate their Trott, Edwards Fisher, and Mund apartment buildings, constructed...

**Services:** [Building Enclosure Rehabilitation](#)

**Markets:** [Residential - Apartment](#)

**Keywords:** [Condition Assessment](#), [Condition Assessment-Multi-Building](#), [Masonry](#), [Masonry-Brick](#), [Senior Housing](#)



## Wadsworth Atheneum

**Hartford, CT**

The Wadsworth Atheneum is a multi-building art museum complex built between 1842 and 1950. The atheneum suffered from water leakage that was damaging decorative plaster, threatening art storage...

**Services:** [Building Enclosure Rehabilitation](#)

**Markets:** [Cultural](#)

**Keywords:** [Condition Assessment-Multi-Building](#), [Historic](#), [Museum](#), [National Register of Historic Places](#), [Preservation Technology](#), [Roofing](#), [Skylight](#), [Walls](#)



## California Department of Parks and Recreation, Columbia State Park

**Columbia, CA**

**Project Contacts:** [CeCe Louie](#), [Carolyn Searls](#)

The National Historic Landmark District of Columbia State Historic Park is a mid-nineteenth-century gold rush town that has been in varying degrees of continuous use since the town's inception. ...

**Services:** [Building Enclosure Investigation](#)

**Markets:** [Cultural](#)



**Keywords:** Condition Assessment-Multi-Building, Glass and Glazing, Historic, Masonry-Brick, National Register of Historic Places, Preservation Technology , Walls, Windows, Wood, Wood Frame



## Middlebury College, Bread Loaf Mountain Campus

**Middlebury, VT**

**Project Contacts:** [Matthew Bronski](#), [Jeffry Ceruti](#), [Stephen Ruggiero](#)

The Bread Loaf Mountain Campus of Middlebury College is the home of the Bread Loaf School of English, the Bread Loaf Writer's Conference, and other summer programs run by the college. The campus...

**Services:** [Building Enclosure Rehabilitation](#), [Structural Rehabilitation](#)

**Markets:** [Education - College & Prep](#)

**Keywords:** [Condition Assessment-Multi-Building](#), [Deterioration](#) , [Historic](#), [Preservation Technology](#) , [Wood](#), [Wood Frame](#)



## City of Boston Facade Inspection Ordinance

**Boston, MA**

**Project Contacts:** [Nick Floyd](#), [Scott Tomlinson](#)

The City of Boston requires the inspection of exterior walls and appurtenances of buildings as described in Ordinance 9-9.12 of the City of Boston Municipal Code. SGH performs ordinance-compliant...

**Services:** [Building Enclosure Investigation](#)

**Keywords:** [Code Compliance](#), [Condition Assessment-Multi-Building](#), [Facade Inspection](#), [Facade Ordinance](#), [Industrial Rope Access](#), [Ordinance](#)



## Emma Willard School

Troy, NY

**Project Contacts:** [Peter Babaian](#)

The Emma Willard School is the nation's oldest secondary school for girls. The main campus quadrangle is comprised of the original campus building, designed in the Tudor Gothic style and...

**Services:** [Building Enclosure Rehabilitation](#)

**Markets:** [Education - K-12](#)

**Keywords:** [Condition Assessment-Multi-Building](#), [Historic](#), [Masonry](#), [Preservation Technology](#), [School](#), [Structural Stabilization](#)



## Post-Hurricane Katrina Evaluations, St. Bernard Parish

New Orleans, LA

**Project Contacts:** [Peter Nelson](#), [Eric Olson](#)

In August 2005, Hurricane Katrina devastated St. Bernard Parish, located east of New Orleans, with high winds, heavy rains, and flooding due to failure of levees surrounding the parish. SGH...

**Services:** [Building Enclosure Investigation](#), [Structural Investigation](#)

**Keywords:** [Condition Assessment-Multi-Building](#), [Damage](#), [Flood](#), [Roofing](#)



## Massachusetts School Building Authority, Building Enclosure Commissioning

Statewide, MA

**Project Contacts:** [Peter Babaian](#), [Jeffry Ceruti](#)

SGH is a Building Enclosure Commissioning Agent for the Massachusetts School Building Authority. SGH has participated in both whole building commissioning in partnership with a Mechanical...

**Services:** [Building Enclosure Rehabilitation](#)

**Markets:** [Education - K-12](#)

**Keywords:** Building Enclosure Commissioning, Building Science, Condition Assessment-Multi-Building, Field Testing



## Post-Hurricane Sandy Evaluations

**NY**


**Project Contacts:** [Nathaniel Smith](#), [Milan Vatovec](#)

On 29 October 2012, Hurricane Sandy made landfall along the eastern United States seaboard, bringing high winds and a tidal surge, and causing billions of dollars in damage to our built...

**Services:** [Structural Investigation](#)

**Markets:** [Residential - Single Family](#)

**Keywords:** [Condition Assessment](#), [Condition Assessment-Multi-Building](#), [Damage](#), [Flood](#)



## The First Church of Christ, Scientist

**Boston, MA**

**Project Contacts:** [Susan Knack-Brown](#), [Matthew Sherman](#)

In the late 1960s, The First Church of Christ, Scientist (TFCCS) retained I.M. Pei & Partners and Araldo Cossutta, Associated Architects to design the fourteen-acre Christian Science Plaza...

**Services:** [Building Enclosure Investigation](#), [Building Enclosure Rehabilitation](#)

**Markets:** [Religious](#)

**Keywords:** [Concrete](#), [Concrete Rehabilitation](#), [Condition Assessment-Multi-Building](#), [Facade Inspection](#), [Field Testing](#), [Industrial Rope Access](#), [Laboratory Testing and Analysis](#), [Nondestructive Testing](#), [Petrography](#), [Plaza](#), [Preservation Technology](#), [Signature Project](#), [Water Leakage](#)